
# **SCHEDULE OF CONDITION**

### **A Public House** in Kent



FOR


### Mr S

**Prepared by:** 

### **INDEPENDENT CHARTERED SURVEYORS**

### **CONTENTS**

### SCHEDULE OF CONDITION



**Independent Chartered Surveyors** 

Prospective Tenant:	Mr S	
Repairing Covenant, Redecorating Covenant, Reinstatement and Statutory Regulation Covenant	We have not seen a copy of the lease and we have therefore assumed the property has a full repairing and insuring covenant – or will have under the proposed lease. We	
Yield Up Clause:	have assumed it is a standard lease with no unusual or onerous clauses. Your Legal Adviser should confirm this and advise us of any unusual or onerous clauses immediately.	
Photographs:	We typically take approximately 250 photographs during the course of a Schedule of Condition. We reserve the right to produce these photographs to establish	

Kent

### **Orientation:**

**Address:** 

All directions are taken as if viewing the property from the front.

the condition of the property over and above

the ones included in the report.

The Schedule of Condition offers a detailed description of the condition of the property.

We have not carried out formal investigations to establish if the property is Listed or in a Conservation Area; if it is it will require various permissions to be obtained before work is carried out over and above that normally required, and possibly the use of appropriate materials for the age, type and style of property.

The Schedule of Condition is to be read in conjunction with the Property Report.

**Independent Chartered Surveyors** 

# **ELEVATIONS**

3.00.

All directions given as you face the property.

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants.

opyright

**Independent Chartered Surveyors** 

FRONT ELEVATION Pub Side Trip Century Trip Century Trip Century Trip Century Trip Century			
DESCRIPTION	CONDITION	ACTION REQUIRED	
<b>Roofs:</b> Hipped large clay tile roof with two gables	Awkward valley gutters; some are blocked. Signs of water penetration within function room	Repair and make watertight	
Gutters and Downpipes: Cast iron and plastic	Signs of dampness getting into function room.	Ensure all gutters are watertight and falling towards the downpipe. Repair and secure as necessary, ensure downpipes are clear.	
Walls: Rough cast render With ornate timberwork	Bare timber visible	Repair, prepare and redecorate.	
Vertical decorative tiling	Some tiles missing and cracked	Replace	

Independent Chartered Surveyors —— Marketing by: — www.1stAssociated.co.uk 0800 298 5424

Sliding sash windows to first floor level and ornate picture windows to ground floor with leaded lights	Wet rot found. Also plastic capping over cill to first floor level.	Remove plastic cill, repair and replace timbers generally.
	<u> </u>	
	strad	
	KA99	
CORVINE		
0,		
		6

FRONT ELEVATION Accommodation Side			
1) Pl	th Century blic House	2.00.24	
DESCRIPTION	CONDITION	ACTION REQUIRED	
Chimneys: One brick chimney	Brick deteriorating and spalling.	Repoint and repair	
Roofs: Hipped roof with large clay tiles	SV		
Gutters and Downpipes: Cast iron		Ensure all gutters are watertight and falling towards the downpipe. Repair and secure as necessary, ensure downpipes are clear.	
Walls: Vertical decorative tiling at high level Rough cast white painted render to base	Partly hidden by vegetation growing up the wall and onto the roof.	Cut back vegetation, repair, prepare and redecorate render and vertical tiles.	

Independent Chartered Surveyors
\_\_\_\_\_ Marketing by: \_\_\_\_\_

www.1stAssociated.co.uk 0800 298 5424

Sliding sash windows	Signs of wet rot	Repair, prepare and redecorate.
Entrance porch		
		1
		0.
		ð.
	t st A so	XOT
		60°
	~0~	
	67	
	K	
	× í	
. 07		
STRAC		
0		
COPYTE		

<u>LEFT HAND SIDE ELEVATION</u> (Private living accommodation and pub Area)			
		AF-	
DESCRIPTION	CONDITION	ACTION REQUIRED	
Chimneys: Two brick chimneys:	. ~		
Rear chimney – large brick chimney	Some spalling	Repoint and repair	
See front elevation for other chimney	650		
Roofs:			
Hipped roof with large and small clay tiles	Particularly attention needs to be paid to the small clay tiled area which may need re- roofing.	Re-roof to make watertight	
Flat Roof:			
Not visible	No visible signs of dampness internally		
Gutters and Downpipes: Cast iron		Ensure all gutters are watertight and falling towards the downpipe. Repair and secure as necessary, ensure downpipes are clear.	

vegetation	Cut back v Repair, redecorate	prepare
g to rear left	hand Check t progressiv	o see wh
	progressiv	
wet rot	Repair, redecorate	prepare
5500		

<u>RIGHT HAND SIDE ELEVATION</u> <u>Pub side</u>			
		A.	
DESCRIPTION	CONDITION	ACTION REQUIRED	
<b>Roofs:</b> Hipped roof with large clay tiles	. 8	9 <sup>0</sup> .	
Gutters and Downpipes: Cast iron	A55001	Ensure all gutters are watertight and falling towards the downpipe. Repair and secure as necessary, ensure downpipes are clear.	
Walls: Decorative tiling Ornate black and white timbers	S	Repair, prepare and redecorate.	
Painted rough cast render to low level Smokers canopy area	Hidden by smokers canopy area		
Windows and Doors: Sliding sash windows	Signs of wet rot	Repair, prepare and redecorate.	
Metal Fire Escape:		Prepare, prime and redecorate.	

<b><u>RIGHT HAND SIDE ELEVATION</u></b> (Accommodation side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Roofs:			
Small hipped clay tiled roof	There is a hidden valley gutter in this area which are troublesome and needs inspection.	Re-roofing may be required during the term of the lease.	
Gutters and Downpipes: Cast iron and plastic		Ensure all gutters are watertight and falling towards the downpipe.	
Plastic soil and vent pipes		Repair and secure as necessary, ensure downpipes are clear.	
Walls:			
Mixture of Flemish Bond and English Bond brickwork	Areas of spalling and various bad repairs in cement mortar	Remove cement mortar and replace with lime mortar.	

Windows and Doors:				
Sliding sash timber windows	Signs of wet rot	Repair,	prepare	and
Oriole window		redecorate.		
Bay window	Movement visible	Repair, redecorate.	prepare	and
			. N	
Air Bricks:				
	Indicates suspended timber	ð.		
	floor in this area.	O		
	De la compañía de la comp	2		
	Air brick			
	Stra.			
CORVINS				

<b>REAR ELEVATION</b>			
Pub and p	rivate living accommod	ation	
DESCRIPTION	CONDITION	ACTION REQUIRED	
Chimneys:	67		
One capped chimney	Spalling brickwork, assumed dampness coming into property	Repair and make watertight	
Roofs:	¥		
Hipped with large clay tiles	Awkward valley gutter details	Add a roof hatch to allow access to gain valley gutter. Re-roofing may be required during the term of the lease.	
Small tiles		Repair and make watertight	
<b>Gutters and Downpipes:</b> Cast iron		Ensure all gutters are watertight and falling towards the downpipe.	
		Repair and secure as necessary, ensure downpipes are clear.	

Walls:		
Mixed bond of Flemish and English bond and a Stretcher bond. Made up of a mix of machine and hand cut bricks and napped flint.	Some spalling bricks	Repair, prepare and redecorate.
Ornate timber	Cracking to rear left hand side	1
Vertical tiling		
Rough cast render to lower level	Crack to left hand corner (all directions given as you face the property) and	Repair, prepare and redecorate.
Metal corrugated sheet to entrance to cellar		
Windows and Doors:	OY	
Painted casement	Marked	Repair, prepare and redecorate.
Picture windows		
Sliding sash timber windows Trees:	X	
Large trees to the rear of the pub		Reduce in size
CORYTHE		

<u>ROOFS</u>			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Main Roof to pub:			
Large clay tile	Problems with awkward valley gutters	Repair and make watertight	
Main Roof to private living accommodation:	X		
Large clay tile and small hand made clay tile	Dampness getting in main roof void	Re-roof and repair during duration of lease	
Valley Gutters:	Areas of blocked valley gutters and deterioration to front left hand side and rear side of function room indicating water has been getting into these areas.	Repair and make watertight	
High Level Flat Roof: Not visible			
Low Level Flat Roof:			
Felt covered	Flat felt roof to right hand side	Requires a reflective paint, ideally replacing with high performance felt	

Independent Chartered Surveyors ——— Marketing by: —— www.1stAssociated.co.uk 0800 298 5424

Splayed Bay Window Roof:		
Small lead flat roof	Movement – we believe there to be water problems here	Repair and make watertight

**Independent Chartered Surveyors** 

OUTSIDE AREAS		
DESCRIPTION	CONDITION	ACTION REQUIRED
Beer Garden:		
Smoking Area (right hand side): Large tarpaulin on a metal frame on a timber decking with heaters and TV	Smokers area	
Private Gardens to front and rear: Large tree and paved area with wood fence	Fence in need of repair	Repair fence and re-stain
Private garden to rear Outbuilding with concrete panels on walls on one and rendered walls on the other	Possible asbestos roof.	Obtain asbestos report

Independent Chartered Surveyors —— Marketing by: — www.1stAssociated.co.uk 0800 298 5424

Outdoor store attached to rear left hand side: Concrete tile pitched roof Flemish Bond brickwork wall Exposed timbers internally and timber lintels	Wet rot present	Repair, prepare and redecorate.
<ul> <li>Outdoor Bowing Alleys to rear (pub side)</li> <li>No. 1 to left hand side</li> <li>Asbestos sheet to roof Single pitch timber frame Rendered blockwork</li> <li>No. 2 left hand side</li> <li>Plastic corrugated sheet roof with timber running across it Blockwork with rough cast render</li> </ul>	Skittle alley No. 1         Skittle alley No. 2	Repair, prepare and redecorate.
Children's Play Area to rear:		
Pre-fabricated glass fibre tree	Not to ROSPA standards. Landing area with no segregated area and DIY standard.	

Barbecue and Barbecue Area to rear:		
<b>Barbecue Area:</b> Timber slatted roof with Timber frame	Water coming through on the day of our survey	Legal adviser to check and confirm there is planning permission / building regulations for these areas or suitable permissions for them to be temporary structures
	Equipment not checked	C
	Assumed a temporary	
Barbecue:	structure.	
Pre-profile metal hipped roof Timber Frame Barbecue Equipment	BBQ	
Trees to rear:	2	
Two large trees adjacent to rear ladies toilets	Signs that a further tree has been cut down	Need cutting back and maintaining. If left will affect the building.
copyright		

# **INTERNAL**

All directions given as you face the property.

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or rin. appropriate agreed monetary compensation in lieu of this to the new tenants

**Independent Chartered Surveyors** 

<u>Cold Cellar</u>			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:			
Boarded	Staining and damp ingress from bar above.	Repair leak and replace boarding and redecorate whole of ceiling.	
CORVILLE			

Walls:		
Concrete	Dampness visible and coming through	Remove mould, repair, prepare and redecorate.
Metal structural frame visible in cellar area	This supports the floors above it needs to be kept free of corrosion.	Keep free of corrosion
	Metal structural frame	
Floors:	• 67	
Concrete and briquettes	Marked	Clean and/or replace and leave a smooth impervious surface
	Briquettes	
Store Area:	Fore area	
Steps:		
Full head height,	Marked. Noted it only had	Repair, prepare and
corrugated roof section above.	temporary repairs.	redecorate.

Independent Chartered Surveyors —— Marketing by: — www.1stAssociated.co.uk 0800 298 5424

Services:		
Electrics	Electrics	
Drop:		
	Wear and tear around drop area	Repair, prepare and redecorate
	Drop area	. d O
opination	sta	

# **GROUND FLOOR TRADING AREA**

**Independent Chartered Surveyors** 

<u>Main Bar</u> (Open Plan)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:	<u>c</u>		
Embossed paper	Dated	Repair, prepare and redecorate.	
Walls:	6		
Drop beams and columns (assumed part of the structural frame that goes up into the function room and down into the cellar)	Marked / average / dated	Repair, prepare and redecorate	
Pool table to left hand side TV and pull down screen to right hand side	Average / dated		

Carpet	Ingrained dirt	Clean or replace
Carpet tiles around pool table	Ingrained dirt	Replace
Joinery:		
Large picture windows with leaded lights and opaque glass to top	Average / Marked	Repair, prepare a redecorate.
Doors	Marked	Repair, prepare a redecorate.
	stracio	
CORNER		
CORVIN		



Sanitary Ware		
Four urinals, one WC and one wash hand basin	Dirty	Deep clean
Joinery:		
Flush doors	Marked	Repair, prepare and redecorate.
A	Stand	

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		· · ·
Painted	Average / Dated	Repair, prepare and redecorate
Walls:		0
Painted	Marked	Repair, prepare and redecorate.
Manhole	-0°*	
Floors:	69	
Quarry tiles	Ingrained dirt	Deep clean
Joinery:	S	
Doors	Marked	Repair, prepare and redecorate.
CORSTAN		

Ladies' Toilets (left hand side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:	0		
Painted	Average and dated	Repair, prepare and redecorate	
Walls:	C Y		
Floor to ceiling tiles	Average	Clean	
Floors:			
Quarry tiles to WC area	Dirty	Deep clean	
Carpet	Ingrained dirt	Clean /or replace	
Sanitary Ware:			
One WC, one wash hand basin	Dated	Deep clean	
Joinery:			
Flush doors	Marked	Repair, prepare and redecorate.	

Lobby Area to Ladies Toilets			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:			
Painted	Average / dated	Repair, prepare and redecorate	
Walls: Painted	Marked	Repair, prepare and redecorate.	
Floors:	C)		
Carpet	Ingrained dirt	Deep clean	
Joinery:	67		
Flush Doors	Marked	Repair, prepare and redecorate.	
CORVINE			

<u>Corridor</u>				
DESCRIPTION	CONDITION	ACTION REQUIRED		
Ceilings:				
Textured paint	Marked	Repair, prepare and redecorate		
Walls:				
Painted	Marked	Repair, prepare and redecorate		
Floors:	°			
Carpet	Ingrained dirt	Clean / replace		
copyright	Strag			

<u>Ladies' Toilets</u> (right hand side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings: Textured paint	Marked	Repair, prepare and redecorate	
Walls: Floor to ceiling tiles Cupboard	Ingrained dirty Blown tiles next to window	Repair, prepare and redecorate.	
Floors: Quarry tiles next to WC area Carpet	Ingrained dirt Ingrained dirt	Deep clean Clean/ replace	
Sanitary Ware: Two WC's, one wash hand basin and one vanity unit	Ingrained dirt	Deep clean	
Joinery: Two windows	Marked	Repair, prepare and redecorate.	
Flush doors	Marked	Repair, prepare and redecorate	

# **GROUND FLOOR**

## **BACK OF HOUSE**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants.

**Independent Chartered Surveyors** 

Bar Servery Area			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Bar:	C)Y		
Optics to back bar	Average	Clean and/or repair	
Wooden front with vertical timber slatted bar and top	Average	Clean and/or repair	
Floors:	G		
Altro style flooring with graphite finish with metal trims part way through	Ingrained dirt	Clean or replace	
COPYING			

Office to front left hand side		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	6	
Old style artex/asbestos lath and plaster ceiling	Hairline cracks	Repair, prepare and redecorate.
Walls:	G	
Fake timber boarding	Marked	Repair, prepare and redecorate.
Floors: Laminate	Average	Clean
008	1	

Joinery:		
Sliding sash windows	Marked External window of office area - soft rot round	Repair, prepare and redecorate.
One external door and Two four panel internal doors	Marked Dated and stained	Repair, prepare and redecorate.
Constant	st	

Food, Sprits and General Store		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	O7	
Variety of surfaces	Slight damage and uneven	Skim coat plaster, repair, prepare and redecorate.
Walls:		
Outside walls are rendered	Render and various other finishes	Repair, prepare and redecorate
	Movement to left hand corner of room	Repair, prepare and redecorate.
Floors:		
Concrete With step (not ideal)	Marked	Level and apply floor paint, prepare and redecorate
Joinery:		
Three fixed timber windows with Georgian plated glass	Marked	Repair, prepare and redecorate.
Doors		Repair, prepare and redecorate.

# **GROUND FLOOR**

## **PRIVATE LIVING ACCOMMODATION**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants.

**Independent Chartered Surveyors** 

Front Lounge		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	<u>c</u>	
Painted lath and plaster	Some undulations	Repair, prepare and redecorate
Walls:	9	
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Laminate	Marked	Clean
Joinery:		
Sliding sash windows Doors	Soft rot	Repair, prepare and redecorate. Repair, prepare and redecorate.

<u>Rear Dining Area</u>		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	C)	
Painted	Average	Repair, prepare and redecorate.
Walls:		Dancin manager and
Painted woodchip	Average	Repair, prepare and redecorate
Floors:		
Vinyl	Average	Clean
Joinery:		
Windows	Likely to have some wet rot in main front of the frame.	Repair, prepare and redecorate.
Doors		Repair, prepare and redecorate.

Independent Chartered Surveyors
\_\_\_\_\_ Marketing by: \_\_\_\_\_

www.1stAssociated.co.uk 0800 298 5424

Domestic Kitchen		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	<u>e</u> Y	
Painted with central spine beam	Average	
Walls:	- G*	
Painted	Average	
Wall and floor units	5	
Floors:	Y	
Vinyl wood look flooring	Average	
Joinery:		
Two top hung painted timber casement windows	Average	
Doors	Average	
External door to garden		

## FIRST FLOOR

## **FRONT OF HOUSE**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

3.00

**Independent Chartered Surveyors** 

Large Function Room		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:	e e e e e e e e e e e e e e e e e e e	
Painted embossed paper	Average. Looks like there has been previous water leaks.	Make roof watertight and repair, prepare and redecorate
Walls: Painted boarding	Average	
Dado rail and large skirting Four cast iron circular columns (part of structural frame coming from cellar)		
Floors:		
Central vinyl floor covering	Marked	Clean
Carpet surround	Worn	Replace

Joinery:		
Three sets of sliding sash windows – 3 x 4 panes to top sash	Wet rot Note all of the window cills have been overclad in plastic and there is likely to be deterioration in the timber window cill beneath	Remove plastic cill, repair cill and repair, prepare and redecorate windows as a whole.
Doors	Marked	Repair, prepare and redecorate.
o de	sta	

Small Function Room		
DESCRIPTION	CONDITION	ACTION REQUIRED
<b>Ceilings:</b> Lath and Plaster painted	Hairline cracking	Repair, prepare and redecorate.
Walls: Painted woodchip	Marked Hairline cracking to front left hand corner and looks to have been a chimney removed to front wall.	Repair, prepare and redecorate.
Floors: Carpet	Worn and stained	Clean and/or replace
Joinery: Three sets of sliding sash windows – 3 x 4 panes to top sash	Wet rot Note all of the window cills have been overclad in plastic and there is likely to be deterioration in the timber window cill beneath	Repair, prepare and redecorate.
Doors Security access	Marked	Repair, prepare and redecorate.

Shared Access Corridor		
		J.
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted textured	Marked	Repair, prepare and redecorate.
Walls:		0
Woodchip painted	Marked	Repair, prepare and redecorate.
Floors:	29	
Vinyl tiles	Ingrained dirt	Clean and/or replace
copyright		

Staircase		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Hairline cracking and marked	Repair, prepare and redecorate.
Walls:		
Painted woodchip	Marked and impact damage	Repair, prepare and redecorate.
Wood panelling	Average	
Floors:		
Carpet	Ingrained dirt	Clean and/or replace
CORVINE		

## FIRST FLOOR

## **BACK OF HOUSE**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants essocial contraction of the second se

**Independent Chartered Surveyors** 

------ Marketing by: -----www.1stAssociated.co.uk 0800 298 5424 50

<section-header></section-header>		
DESCRIPTION	CONDITION	ACTION REQUIRED
Formed in a wood carcass and wood boarding to front Dumb waiter behind bar Back bar with optics	Wear to bar top	Repair, prepare and redecorate.
CORMENT		

Catering Kitchen			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:			
Painted textured (not ideal)	Water leak/damage to front right hand side	Repair, prepare and redecorate.	
Walls:	K)		
Painted with splash back tiles, three tiles high around kitchen unit	Kitchen units are of basic quality	Repair, prepare and redecorate.	
Floors:			
Vinyl	Marked	Clean and/or replace	
Joinery:			
Splayed bay window		Repair, prepare and	
Doors		redecorate. Repair, prepare and redecorate.	
Dumb Waiter:			
Access to dumb waiter			

#### **Catering Equipment:**

The catering equipment has not been inspected, as we are not expert in this area, you should seek expert advice. We have assumed that the catering equipment meets Local Authority approval and is appropriate for use.

From what we could see it was to a domestic standard, rather than a commercial catering standard.

convitent stand Services: See Services section

**Independent Chartered Surveyors** 

## **FIRST FLOOR**

# **PRIVATE LIVING ACCOMMODATION**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

**Independent Chartered Surveyors** 

Bedroom One (Rear Right Hand)         Image: Constraint of the second s		
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings: Painted lath and plaster Roof access	Undulations	Repair, prepare and redecorate
Walls:     Painted woodchip     Fireplace	Average Vented	Repair, prepare and redecorate
Floors: Carpet	Marked with iron burns around chimney	Clean or replace
Joinery: One double hung timber casement window Plank door	Marked Marked	Repair, prepare and redecorate. Repair, prepare and redecorate.

Bedroom Two         (Left hand side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:	57		
Lath and plaster	Marked	Repair, prepare and redecorate	
Walls:			
Painted woodchip	Slightly marked above bed area	Repair, prepare and redecorate	
Floors:			
Carpet	Average Clean or replace		
Joinery:			
Sliding sash window	Marked	Repair, prepare and	
Plank door	Marked	redecorate. Repair, prepare and redecorate.	

Bedroom Three (Single bedroom to rear left hand side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:	ST ST		
Painted	Average	Repair, prepare and redecorate	
Walls:	×		
Painted	Average	Repair, prepare and redecorate	
Floors:			
Carpet	Average	Clean or replace	
Joinery:			
Window	Wet rot	Repair, prepare and redecorate.	
Door	Average	Repair, prepare and redecorate.	

Independent Chartered Surveyors
\_\_\_\_\_ Marketing by: \_\_\_\_\_

www.1stAssociated.co.uk 0800 298 5424

<u>Bathroom</u> (rear left hand side)			
DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:	.9		
Textured paint	Average	Repair, prepare and redecorate.	
Walls:	9		
Floor to ceiling tiles	Some re-grouting needed Signs of water leaks around bath.	Clean and re-grout, particularly to the rear left hand corner where there is mould.	
Floors:			
Carpet	Average Clean or replace		
Joinery:			
Windows	Wet rot found outside	Repair, prepare and redecorate.	
Doors	Average	Repair, prepare and redecorate.	

Sanitary Ware:		
Bath, wash hand basin and WC and shower unit	Mould around bath. Heavily masticed indicating a leak.	Deep clean and re-grout
	Mould around bath	St.
		60.00.
	55001	
	ST	
Children and a start of the sta		
COX		

<u>Corridor</u>			
DESCRIPTION	CONDITION	ACTION REQUIRED	
<b>Ceilings:</b> Painted lath and plaster	Undulations	Repair, prepare and redecorate.	
Walls: Painted woodchip	Average	Repair, prepare and redecorate	
Floors: Carpet	Ingrained dirt	Clean and/or replace	
CORVINE	SAS		

### **OTHER MATTERS**

### **SERVICES**

### **Electrics**

All electrics need to be tested by an NICEIC approved electrician or equivalent to Institute of Electrical Engineers (IEE) standard. Note our comments with regards to the lights and the extract system.

### Fuel – Gas/Oil

The respective safety standards to be applied and most full repairing and insuring leases require a test certificate. All services to Gas Safe Standard or equivalent.

### **FIRE REGULATIONS**

Normally it is a requirement of any Lease or Tenancy agreement that current fire regulations are adhered to and that a service contract is in place. This is how the property should be left.

**ACTION REQUIRED:** You should have a suitable Fire Safety Notice from the outgoing tenant/landlord.

### **DISABILITY DISCRIMINATION ACT**

You should be aware that it is now a requirement to give reasonable access to the disabled and make reasonable amendments to the property as is necessary to accommodate them. It is a condition of all the leases that we have seen to meet this requirement.

**ACTION REQUIRED:** You should ask to see if a report has been carried out in line with the Disabilities Act highlighting areas that can be improved or have been improved.

**Independent Chartered Surveyors** 

### ASBESTOS REGISTER

In a property of this age there may well be some asbestos. This was commonly used post war until it was banned only in the last ten or so years, although it is rumoured that it was still used after this point in time.

It is now a requirement for any public building to have an asbestos register, indicating whether there is or is not asbestos and if so where it is.

**ACTION REQUIRED:** An Asbestos Register should be provided by the outgoing tenant/landlord.

You should note that work involving products containing asbestos is covered by Health and Safety legislation and you are recommended to seek the advice of the Local Authority Environmental Health Officer before proceeding with any such work.

We are not asbestos surveyors.

**Independent Chartered Surveyors** 

### **LIMITATIONS**

As per our original Terms of Engagement, we would remind you specifically that:

We have not inspected parts of the structure that were covered, unexposed or inaccessible during our inspection. We therefore cannot confirm that such parts are free from defect, structural or otherwise.

We have not determined whether any hazardous materials such as high alumina cement, calcium chloride, asbestos etc have been used in the construction.

Our report is for the use of the party to whom it is addressed above and no responsibility is accepted under the Third Parties Act or for any third parties who use this report in whole or in part.

We have not carried out a comprehensive test of any electrical, mechanical or drainage services. We therefore cannot confirm that they are operational and in good condition. If you wish us to arrange tests please advise.

We have not carried out or arranged for specialists to undertake any reports, for example an environmental report or an audit report upon the property. We are therefore unable to advise whether any contaminated or other adverse environmental issues affect the site.

This report does not constitute a Structural Survey (now known as a Building Survey).

**Independent Chartered Surveyors** 

#### Signature Document in Relation to A Public House in Kent

#### **Schedule of Condition**

This signature document represents page 65 and 66 of a 66 page Schedule of Condition relating to:

A Public House in Kent

as prepared by

**Chartered Surveyors** 

You should ensure your Legal Advisor gets this document signed by the relevant parties and agreed prior to legal commitment to purchase. Delete/amend as you require.

#### **Lessees Representative**

We verify that this is a true and accurate record of the condition of:

A Public House in Kent

As inspected

By

**Chartered Surveyors** 

Signed: ..... Dated:

For and on Behalf of Chartered Surveyors

**Independent Chartered Surveyors** 

#### Lessee

Mr S has seen and forwarded this document on by recorded delivery on ..... to the owners/landlords or their legal representatives in relation to the proposed Lease.

Signed: Dated: Dated:

#### Landlords Representative (delete as applicable)

Print Name: ..... for and on behalf of ..... has inspected and read the Schedule of Condition for an on behalf of ..... and accepts that it is a true and accurate record.

Signed:		•	Dated:	
-	• 25			
For and	on Behalf of:			

I have the authority to sign this document on behalf of the aforementioned company.

**Independent Chartered Surveyors**