### **SCHEDULE OF CONDITION**

#### Of a Restaurant In Hertfordshire



**FOR** 

#### Miss Q

Prepared by:

INDEPENDENT CHARTERED SURVEYORS

Marketing by: www.1stAssociated.co.uk 0800 298 5424

#### **CONTENTS**

#### **SCHEDULE OF CONDITION**

Elevations	page 4
Internal Rooms GROUND FLOOR TRADING AREA GROUND FLOOR BACK OF HOUSE	<b>page</b> 18
FIRST FLOOR BACK OF HOUSE FIRST FLOOR BACK OF HOUSE	
Limitations	page 75
Signature Document	page 76

Address: Restaurant

Hertfordshire

**Prospective Tenant:** Miss Q

Repairing Covenant, Redecorating Covenant, Reinstatement and Statutory Regulation Covenant Yield Up Clause: We have not seen a copy of the lease and we have therefore assumed the property has a full repairing and insuring covenant – or will have under the proposed lease. We have assumed it is a standard lease with no unusual or onerous clauses. Your Legal Adviser should confirm this and advise us of any unusual or onerous clauses

immediately.

**Photographs:** We typically take approximately 100

photographs during the course of a Schedule of Condition. We reserve the right to produce these photographs to establish the condition of the property over and above the

ones included in the report.

**Orientation:** All directions are taken as if viewing the

property from the front.

The Schedule of Condition offers a detailed description of the condition of the property.

We have not carried out formal investigations to establish if the property is Listed or in a Conservation Area; if it is it will require various permissions to be obtained before work is carried out over and above that normally required, and possibly the use of appropriate materials for the age, type and style of property.

The Schedule of Condition is to be read in conjunction with the Property Report.

#### **ELEVATIONS**

All directions given as you face the property.

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants.

#### **FRONT ELEVATION**



DESCRIPTION	CONDITION	ACTION REQUIRED
Chimneys:		
Front left hand chimney brick built	Average	Repoint to make watertight
Rear left hand chimney brick built	Average  Rear left hand chimney	Repoint to make watertight
Roofs:	·	
Pitched clay tiles	Heavily damaged to section we can see to the rear.	Repair and make watertight
Gutters and Downpipes:		
Box gutter	Leaking	Ensure all the box gutters are watertight and falling towards the downpipe.  Repair and secure as necessary, ensure downpipes are clear.

		T
Walls:		
Stretcher Bond brick at high level	Allowing lateral dampness through	Repoint and repair as necessary
Render at low level and around central window	Hairline cracking and flaking paintwork	Repair, prepare and redecorate
Windows and Doors:		
Eleven Georgian windows; ten are 6 x 6 panels and the central one is an 8 x 12.	Generally deteriorating	Repair, prepare and redecorate / consider replacement
Picture windows	Marked	Repair, prepare and redecorate
Wide window cill to shop front window	People waiting at the nearby bus stop use the window cills of the Dragon King as the bus stop extra seating causing damage to the window cills	Repair, prepare and redecorate
	Window cill needs redecoration	

#### **LEFT HAND SIDE ELEVATION**



Rear left hand side

DESCRIPTION	CONDITION	ACTION REQUIRED
Chimneys:		
See front elevation		
Roofs:		
Pitched clay tile roof – see front elevation		
Profile metal sheeting	Leaks to box gutter side	Repair and make watertight
<b>Gutters and Downpipes:</b>		
Downpipe from box valley gutter – mixture of cast iron and plastic	Leaking	Ensure all box gutters are watertight and falling towards the downpipe.  Repair and secure as necessary, ensure downpipes are clear.

Walls:		
Brickwork parapet wall	Due to the lighter colour we believe it may have been damaged by water or rebuilt.	Repair and make watertight
Painted rendered in Stucco style	Render deteriorating	Repair, prepare and redecorate
Windows and Doors:		
Four Georgian six x six windows.	Deteriorating	Clean, repair, prepare and redecorate.
Three picture windows at ground floor level Third picture window has a fire exit	Deteriorating	Repair, prepare and redecorate
in it.  Timber cills to base	Deteriorating	Repair, prepare and redecorate

The parking directly outside is not connected to the property.

#### **RIGHT HAND SIDE ELEVATION**



DESCRIPTION	CONDITION	ACTION REQUIRED
Chimneys:		
Please see front elevation		
Roofs:		
Please see front and rear elevations		
Clay tiles	Not able to view	Access via cherry picker to view roof, we advise before completing on the lease

Gutters and Downpipes:		
Two plastic downpipe with hopper head	Discharging against wall Drains blocked with rubbish  Hopper head not large enough for downpipes  Downpipes discharging onto wall	Ensure all gutters are watertight and falling towards downpipes and that the hopper heads are large enough and clear drains.
Walls:		
Stretcher Bond brickwork	Some lateral dampness coming in.	Repoint as necessary and check box gutter above.
Five rendered panels Rough cast render	Lateral water damage is occurring in this area. It may relate to the box gutter or the render.	Check box gutter and also repair render as necessary to stop dampness coming in.
Windows and Doors:		
Five metal Crittle style casement windows		Ease and adjust, apply a rust stop paint and repair, prepare and redecorate.
Two casement windows with exposed concrete lintels	Crittle window	Clean, repair, prepare and redecorate.
Driveway Area:		
Concrete  Parking and loading bay, used as a		We assume the access is shared
bin store		
Trees:		
Two trees		Keep maintained

#### **REAR ELEVATION**





Rear ground floor

Rear first floor



Blocked up windows to rear

DESCRIPTION	CONDITION	ACTION REQUIRED
Chimneys:		
Please see front elevation		
Roofs:		
Clay tiles	Badly damaged roof tiles  Damaged tiles	Repair roof tiles; approximately 25% of the entire roof that was visible needed repairing.

Gutters and Downpipes:		
Large hopper head		Ensure all gutters are watertight and falling towards the downpipe. Repair and secure as necessary, ensure downpipes are clear.
Walls:		
Rough cast render at high level (first to second floor level)	Splits to top of render	Repair, prepare and redecorate.
Smooth render at lower level (ground to first floor level)	Marked	Repair, prepare and redecorate.
Concrete painted black plinth along base	Vertical cracking to end and general vegetation	Repair, prepare and redecorate.
Concrete column, clad in brickwork	Extensive damage, including a vertical crack that runs height of building, indicating movement in structure	Exclude from lease
Windows and Doors		
Rear of single storey section (blocked up windows)	Moss and mould starting to occur at base	Mastic seal around window edge where it has opened up.
Variety of casement windows at first floor level	Marked and deteriorating	Clean, repair, prepare and redecorate.

0800 298 5424

#### **ROOFS**

DESCRIPTION	CONDITION	ACTION REQUIRED
Main Roofs:		
Clay tiles	Heavily damaged; approximately 20% of what we could see  Damaged tiles	Replace tiles
	Damaged tiles	
Parapet Wall:		
Box gutter	Signs of water dampness internally  Parapet wall	Repair and make watertight
	Box gutter	
	Drain box gutter discharges to	

**GEM Associates Limited** 

**Independent Chartered Surveyors** 

## **Profile Metal Roof:** Poor detailing, believed to be Repair and make watertight. Box gutter leaking Profile metal roof Close up view Close up of box gutter **Asphalt Roof:** To perimeter - limited view due to We noted the extract fans access restriction were discharging directly on to it. Asphalt roof towards rear of property Extract fans discharging directly onto roof **Roof Space:** There was access and a close boarded roof Inside roof looking towards rear

Inside roof looking towards front

**Independent Chartered Surveyors** 

----- Marketing by: www.1stAssociated.co.uk
0800 298 5424

#### **LOADING BAY AREA**



DESCRIPTION	CONDITION	ACTION REQUIRED
Loading Area:		
A raised area with timber decking and brick columns. We assume these are around a structural frame  Parking and loading bay, used as a bin store	Cracking to column  Cracking to column	Open up and investigate reason for cracking. It could relate to problems with the structural frame. We recommend the structural frame is excluded from the lease.
Sitting Out Area:		
Pre-cast concrete	Minor deterioration	Repair
	Sitting out area	

**Independent Chartered Surveyors** 

Joinery:		
Double timber entrance doors	Marked	Repair, prepare and redecorate.
Steps:		
Steep stone built steps		

## **INTERNAL**

All directions given as you face the property.

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants.

# GROUND FLOOR TRADING AREA FRONT OF HOUSE

#### Restaurant Area Banqueting Area to Left





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Dated and marked	Repair, prepare and redecorate.
Walls:		
Painted at high level	Dated and marked	Repair, prepare and redecorate
Stained timber dado at low level	Marked	Re-stain
Floors:		
Quarry tiles	Ingrained dirt	Deep clean

0800 298 5424

Joinery: Windows	Boarded over	
Inner double stained timber fire exit doors to right hand side	Marked	Re-stain
Outer double stained timber fire exit doors	Marked, particularly to base.	Re-stain  It was noted the fire exit was not working — ensure that fire alarm system is working fully.

#### Restaurant Area Raised Area to Left



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted plaster with decorative moulding with inset lights	Some areas look to have been repaired	Repair, prepare and redecorate.
Walls:		
Timber floor to ceiling with mirrors	Minor marks	Repair, prepare and redecorate
Floors:		
Black tiles	Joints gone in some areas Some cracked tiles	Re-joint and repair/replace
Joinery:		
Picture windows	Marked	General clean and redecorate.
Single fire exit door on left	Limited access due to cars parked in this area	Recommend external signage

# Restaurant Area Waiting Area / Casual Dining to Right



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:  Painted with timber coving Inset lights	Marked	Repair, prepare and redecorate
Walls: Painted	Marked	Repair, prepare and redecorate
Timber dado at low level to approx one metre in height  Two large Chesterfields	Damaged  Damage to timber dado	Repair, prepare and redecorate
Floors: Quarry tiles	Ingrained dirt	Deep clean
Joinery: Picture window	Marked	Clean

**GEM Associates Limited** 

**Independent Chartered Surveyors** 

www.1stAssociated.co.uk
0800 298 5424

#### **Less able/Disabled Toilets / Baby Changing Area**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		D
Painted with extract fan and bulk head light	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Tiles	Ingrained dirt	Deep clean
Sanitary Ware		
WC adapted for the disabled, one small wash hand basin, toilet roll holder, soap dispenser, towel dispenser and warm air hand dryer	Marked	Deep clean
Baby changing area		
Joinery:		
Door	Marked	Repair, prepare and redecorate.

**GEM Associates Limited** Independent Chartered Surveyors

www.1stAssociated.co.uk
0800 298 5424

#### **Lobby Area to Toilets, Loading Bay and Cellar**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted Timber arcatraves	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Veneer timber floor	Some joints opening up	Repair and clean
Joinery:		
Doors	Marked	Repair, prepare and redecorate.

Right Hand Room
(being used as an ice maker / dessert store)

(next to Disabled Toilets)

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted Fluorescent light	Signs of repair	Repair, prepare and redecorate.
Walls:		
White melamine	Marked	Repair, prepare and redecorate.
Floors:		
Tiled	Ingrained dirt	Deep clean
Joinery:		
Door	Marked	Repair, prepare and redecorate.

Outer Lobby Area (giving access to fire doors)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Heavily marked	Repair, prepare and redecorate.
Floors:		
Vinyl	Damaged	Repair/replace
Joinery:		
Double painted timber door which is a fire exit	Damage around push/pull bar and marked	Repair, prepare and redecorate.

#### <u>Ladies Toilets</u> and Associated Lobby Area



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted with four bulk head lights and four inset lights. Timber arcatraves	Areas where it has been repainted and marked areas	Repair, prepare and redecorate.
Roof void access	Not viewed	
Walls:		
Painted	Marked Heavy water staining to right hand side near entrance door  Leaking from shower above?	Identify staining, repair, prepare and redecorate.  We did not note any extraction fans so add a working extract system.
Orange and burgundy tile to a tiled dado	Missing tiles	Repair/replace

Floors:		
Tiles	Ingrained dirt and broken tiles	Deep clean and replace broken tiles
Sanitary Ware		
Five WC's, four wash hand basins set in a vanity unit and further two wash hand basins in a vanity unit	Dirty	Deep clean
Joinery:		
Windows	Marked	Repair, prepare and
Timber Doors	Marked	redecorate.  Repair, prepare and redecorate.

27

#### **GROUND FLOOR**

#### **BACK OF HOUSE**

All directions given as you face the property

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

#### **Central Bar**

#### (Adjacent to restaurant area)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted plaster with decorative moulding with inset lights	Some areas look to have been repaired	Repair, prepare and redecorate.
Access into ceiling		
Central Servery:		
Glazed back to bar		
Oval shaped bar		
Floors:		
Small white quarry tiles	Ingrained dirt	Deep clean
	Tiles need deep clean	

#### Wash Up and Food Preparation Area

(behind Servery Area)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marks where previous repairs have been carried out	Repair, prepare and redecorate.
Walls:		
Tiles and tiles to pitched underside of stairs	Ingrained dirt	Clean and re-grout as necessary
Stainless steel lining to approx 1.5 metres		
Floors:		
Small quarry tile	Ingrained dirty	Deep clean
Dumb waiters:		
Two dumb waiters going up to catering kitchen on first floor	This has not been tested	Test and obtain certificate for dumb waiters

0800 298 5424

#### **Lobby to WC off Preparation Area**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Flaking paint, we suspect a water leak above. Light removed	Repair, prepare and redecorate Add light
Walls:		
Tiled from floor to ceiling	Ingrained dirt and heavy mould to grout	Deep clean and re-grout.
Floors:		
Tiles	Marked	Deep clean
Joinery:		
Doors	Marked	Repair, prepare and redecorate.

#### $\overline{\mathbf{WC}}$



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Mould  Mould to ceiling	Re-plaster, prepare and redecorate and fit light.
Walls:		
Tiled	Marked	Repair, prepare and redecorate.
Extract fan	Not working at time of inspection	Repair and add as large an extract fan as possible
Floors:		
Tiled with a drain	Ingrained dirt and tiles coming away around drain.  Drain that looks to be blocked	Deep clean floor and re-tile in that area

**GEM Associates Limited** Independent Chartered Surveyors

Marketing by:
www.1stAssociated.co.uk
0800 298 5424

Sanitary Ware:  One WC and one small wash hand basin	Marked	Deep clean
Joinery: Door	Marked	Repair, prepare and redecorate.

#### **BELOW GROUND LEVEL CELLAR**

#### **BACK OF HOUSE**

All directions given as you face the property

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

#### **Stair Access Corridor**

DECCRIPTION	CONDITION	A CEION DEOLUBED
DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Concrete	Marked	Clean
	Wear on floor	
Joinery:		
Doors		Repair, prepare and redecorate.
Steps Cellar:	Heavily worn	Replace nosings and vinyl covering

#### **Boiler Room Area**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Pre-cast concrete, painted black with steel frame visible in some areas	Reinforcement bars are visible and rusting	Investigation needs to be carried out with regard to structural frame and the condition of the floor.
Walls:		
Painted Stretcher Bond brickwork	Signs of dampness to base	Repair, prepare and redecorate.
Floors:		
Concrete	Marked	Clean
Joinery: Doors		Repair, prepare and redecorate.
Services:		
Floor mounted Ideal Mexico and a Megaflow system	Not tested	This needs to be tested and test certificates forwarded to yourself by the
Deep sump pump		landlord/present occupier.

36

0800 298 5424

#### **Store off Services Area**

(viewed by torchlight)

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Pre-cast concrete, painted black	Water staining	Repair, prepare and redecorate.
Walls:		Danair propore and
Painted	Stained Areas of pre-cast concrete frame are corroding	Repair, prepare and redecorate.
Floors:		
Concrete	Partially wet	Deep clean
Joinery:		
Metal clad door	Water damage to base in the form of rusting, indicating the cellar does get damp	Repair, prepare and redecorate.

#### **Access Corridor**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Plasterboard	Black paint starting to flake and water staining	Repair, prepare and redecorate.
Walls:		
Perimeter walls formed in painted Flemish Bond brickwork and English Bond brickwork  Internal walls formed in painted blockwork	Cracking - hairline and horizontal in blockwork adjacent to door to approx 0.5 metres and 200mm	Repair, prepare and redecorate.
Floors:		
Concrete		Deep clean
Joinery:		
Doors		Repair, prepare and redecorate.

#### **Store off of Access Corridor**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Pre-cast concrete	Signs of corrosion and metal reinforcement visible	
Walls:		
Painted	Heavy staining to far right hand corner Visibility to walls limited by stored items	Repair, prepare and redecorate.
Floors:		
Concrete	Marked	
Joinery:		D : 1
Doors		Repair, prepare and redecorate.

# Food Storage Area (right hand side)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Plasterboard	Marked	Repair, prepare and redecorate.
Walls:		
Painted English Bond brickwork to external and blockwork internally	Cracks to blockwork from floor to ceiling; slightly raking through the joints and through blockwork  Crack in wall	Repair, prepare and redecorate.
Two cold storage units	Clack III Wali	
Floors:		
Concrete	Marked	Clean
Goods Lift:	Not known if working	You need to obtain a test certificate for this.

**GEM Associates Limited** 

**Independent Chartered Surveyors** 

— Marketing by: www.1stAssociated.co.uk 0800 298 5424

#### **Cutlery Store**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Low ceiling	Marked	Repair, prepare and redecorate.
Walls:		
Painted and unpainted blockwork and painted brickwork	Marks and fixing holes	Repair, prepare and redecorate.
Floors:		
Concrete with floor paint	Marked	Redecorate
Joinery:		
Door	Off its hinges	Re-hang.

0800 298 5424

## **Beer Store**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Low plasterboard	Marked	Repair, prepare and redecorate.
Walls:		
Painted and unpainted blockwork Brickwork to perimeter	Vertical crack to approx three quarters of a metre	Repair, prepare and redecorate.
Floors:		
Concrete	Marked	Repair, prepare and redecorate

#### **Furniture Store**

#### (formerly cold cellar)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Plasterboard	Marked	Repair, prepare and redecorate.
Walls:		
Painted brickwork around perimeter		Repair, prepare and redecorate.
New unpainted blockwork to centre		
Floors:		
Painted concrete	Worn and marked	Apply floor paint
Joinery:		
Doors	Marked	Repair, prepare and redecorate.
Services Cupboard:		
With electric unit set within		You will need to obtain test certificates in relation to this.

# **FIRST FLOOR**

# **FRONT OF HOUSE**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

#### **Gentlemen's Toilets**





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted with seven bulk head lights and four inset ceiling lights	Marked	Repair, prepare and redecorate
Walls:		
Tiles from floor to ceiling	Marked and minor damage	Repair, prepare and redecorate or replace
		We did not note any extraction fans so add a working extract system.
Floors:		,
Vinyl	Worn around urinals and WC	Repair and/or replace
Sanitary Ware		
Four wash hand basins set within a vanity unit, six urinals, three WCs	Marks to melamine boarding behind WCs One tap not working at time of survey	Deep clean
Joinery:		
Timber door	Marked	Repair, prepare and redecorate.

#### **Lobby Area**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted with one bulk head light	Marked and previous colour is grinning through	Repair, prepare and redecorate
Walls:		
Painted Embossed paper to base Timber dado	Marked and previous colours grinning through	Repair, prepare and redecorate
Floors:		
Carpet	Worn	Clean and/or replace
Joinery:		
Timber door	Stained	Re-stain

#### **Landing**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted plasterboard with bulk head lights and timber arcatraves	Marked	Repair, prepare and redecorate.
Walls:		Dania anana ani
Painted with dado rail	Marked	Repair, prepare and redecorate
Floors:		
Timber flooring	Marked	Polish and clean
Stairway:		
Carpet	Dirty and nosings not secure	Deep clean and nosings need securing

# **FIRST FLOOR**

# **BACK OF HOUSE**

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

#### **Catering Kitchen**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked and grease stained	Clean, repair, prepare and redecorate.
Walls:		
Tiles	Ingrained dirt	Deep clean
Stainless steel units	Painted over tiles	
Floors:		Doop aloop
Quarry tiles	Ingrained dirt	Deep clean
Joinery:		
Doors	Marked	Repair, prepare and redecorate.

0800 298 5424

Two dumb waiters	This has not been tested	Test and obtain licence for dumb waiters
Goods Lift		
		Lift licence needed
Two walk in units		

#### **Catering Equipment:**

The catering equipment has not been inspected, as we are not expert in this area, you should seek expert advice. We have assumed that the catering equipment meets Local Authority approval and is appropriate for use.

#### **Access to Catering Kitchen**

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings: Painted	Marked	Repair, prepare and redecorate.
Walls: Painted	Marked	Repair, prepare and redecorate.
Floors: Vinyl	Ingrained dirt	Deep clean
Joinery: Painted door	Marked	Repair, prepare and redecorate

# **FIRST FLOOR**

# PRIVATE LIVING ACCOMMODATION

All directions given as you face the property

Under the terms of most Leases there is a redecoration covenant requiring redecoration on termination of the Lease we assume this will take place or appropriate agreed monetary compensation in lieu of this to the new tenants

# <u>Corridor</u>

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Carpet tiles	Worn	Replace

#### Manager's Office



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate
	Damp areas internally. This could be due to defective parapet walls, box gutters or roof.	Make watertight and repair plaster and redecorate.
Floors:		
Carpet	Worn	Replace
Joinery:		
Windows		Repair, prepare and redecorate.
Doors		Repair, prepare and redecorate.

**GEM Associates Limited** 

**Independent Chartered Surveyors** 

www.1stAssociated.co.uk
0800 298 5424

#### <u>Ladies' Living Quarters</u> (Includes shower and WC within it)



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		Repair, prepare and
Painted	Dated	redecorate.
Walls:		
Painted	Marked and there may be dampness coming through the walls  Our view was limited due to the number of beds and amount of stored items in this area.	Check parapet walls externally, repair, prepare and redecorate.
Floors:		
Vinyl	Marked	Replace
Joinery:		
Georgian windows	Need easing and adjusting	Ease and adjust, repair, prepare and redecorate.
Doors		Repair, prepare and redecorate.

0800 298 5424

## **Shower and WC**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked and condensation	Add better extract and repair, prepare and redecorate.
Walls:		
Painted	Marked and condensation	Add better extract and repair, prepare and redecorate
Floors:		
Vinyl	Worn	Replace
<b>Joinery</b> Metal windows	Damaged and rusting	Add rust stop paint and redecorate.
Georgian window WC	Marked	Repair, prepare and redecorate.
Doors	Marked	Repair, prepare and redecorate.
Sanitary Ware:		
One WC and one shower	Marked and worn  WC	Deep clean or replace

## **Lobby / Corridor to Mens' Area**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Vinyl	Marked	Replace
Joinery:		
Doors	Marked	Repair, prepare and redecorate.

#### Mens' Bedroom

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings: Painted	Dated	Repair, prepare and redecorate.
Walls: Painted Two beds	Dated	Repair, prepare and redecorate.
Floors: Carpet	New	
Joinery: Georgian Windows Door	Marked Dated	Repair, prepare and redecorate.  Repair, prepare and redecorate.

#### **Corner Bedroom**





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted	Marked	Repair, prepare and redecorate.
Floors:		
Carpet	Worn	Replace
Joinery:		
Georgian style window Doors	Needs easing and adjusting	Ease and adjust, repair, prepare and redecorate.  Repair, prepare and redecorate.

## **Shower and WC**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and redecorate.
Walls:		
Painted  Dampness coming through	Heavy mould created by shower and dampness coming in  Heavy mould	Check parapet walls externally, repair, prepare and redecorate.
Floors: Vinyl	Worn	Replace
Joinery:		
Crittle Windows	Damaged	Repair, prepare and
Georgian window WC  Black Entrance Door		redecorate.  Repair, prepare and redecorate.

**GEM Associates Limited** 

**Independent Chartered Surveyors** 

www.1stAssociated.co.uk
0800 298 5424

# Sanitary Ware: One WC and shower Taps without tops Replace taps Missing taps

#### **Lobby Area to Fire Escape**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings: Painted	Dated	Repair, prepare and redecorate.
Walls: Painted	Dated	Repair, prepare and redecorate.
Floors: Carpet tiles	Worn	Replace
Joinery: Door	Marked	Repair, prepare and redecorate.

# WC with Shower (blue painted walls)





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked and condensation and lateral dampness  Damp ceiling	Add additional extraction and repair, prepare and redecorate.
Walls:		
Painted	Heavy mould to walls and lateral dampness	Clear mould, repair, prepare and redecorate.
Extract fan		Ensure fan is working / add a larger fan
Floors:		
Vinyl	Worn	Replace

Joinery:		
Metal Windows	Damaged	Repair, prepare and
Door		redecorate.  Repair, prepare and redecorate.
Sanitary Ware:		
One WC and shower	Service duct works to WC have been opened up	Close duct works
	Ductwork open	

#### **Shower**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		D
Painted	Dated	Repair, prepare and redecorate.
Walls:		
Tiled	Water stains around shower	Clean
Extract fan	Dirty	Clean
Floors:		
Tiled	Worn	Replace
Sanitary Ware:		
One WC and shower	Shower heavily used and worn	Replace
Joinery:		
Flush painted doors	Marked	Repair, prepare and redecorate.





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Marked	Repair, prepare and
Loft hatch to roof space	Not inspected	redecorate.
Walls:		
Painted and painted dado effect	Marked	Repair, prepare and redecorate.
Floors:		
Vinyl	Ingrained dirt	Deep clean
Joinery:		
Windows		Repair, prepare and redecorate.
Doors		Repair, prepare and redecorate.

#### **Bedroom – left hand corner of front elevation**

#### (bus stop side – left hand corner room)

DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		Repair, prepare and
Painted	Dated	redecorate.
Blue column running along ceiling		
Walls:		
Painted	Dated	Repair, prepare and redecorate.
Double bunk bed and two beds		
Floors:		
Carpet	Worn	Replace
Joinery:		
Crittle Windows		Repair, prepare and
Georgian window WC		redecorate. Repair, prepare and
Doors		redecorate.

## **Bedroom**



DESCRIPTION	CONDITION	ACTION REQUIRED	
Ceilings:			
Painted	Dated	Repair, prepare and redecorate.	
Walls:			
Painted	Cracking - horizontal Likely to be due to dampness in the structure or could be a structural frame problem.	Repair, prepare and redecorate and check reason for cracking.	
Floors:			
Carpet	Worn	Replace	

0800 298 5424

Joinery:		Repair,	prepare	and
Georgian window left hand side	Problems with water ingress coming in and cills covered up	redecorate.		
	Windows letting in water overlooking courtyard			
Flush painted doors	Marked	Repair, redecorate.	prepare	and

## **Bedroom**





DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		Dania anna al
Painted	Dated	Repair, prepare and redecorate.
Walls:		
Painted	Dated	Check parapet walls externally, repair, prepare and redecorate.
Floors:		
Vinyl	Worn	Replace
Joinery:  Georgian window to rear overlooking metal roof and metal fire escape on first floor level	Marked	Repair, prepare and redecorate.
Flush painted door	Damaged	Repair, prepare and redecorate.

#### **Domestic Kitchen**



DESCRIPTION	CONDITION	ACTION REQUIRED
Ceilings:		
Painted	Heavily stained and cracking	Repair, prepare and redecorate and check reason for cracking
Walls:		
Painted	Marked and cracking around ceiling beams	Repair, prepare and redecorate check reason for cracking
Floors:		
Vinyl	Worn	Replace
Joinery:		
Crittle Windows Georgian window WC	Damaged	Repair, prepare and redecorate.
Flush painted door	No door ironmongery	Add ironmongery, repair, prepare and redecorate
Services:		
Two wall mounted boilers; one Main.BF and one Valliant		Obtain service records

**GEM Associates Limited** Independent Chartered Surveyors

Marketing by: —www.1stAssociated.co.uk

0800 298 5424

#### **OTHER MATTERS**

#### **SERVICES**

#### **Electrics**

All electrics need to be tested by an NICEIC approved electrician or equivalent to Institute of Electrical Engineers (IEE) standard. Note our comments with regards to the lights and the extract system.

#### Fuel - Gas/Oil

The respective safety standards to be applied and most full repairing and insuring leases require a test certificate. All services to Gas Safe Standard or equivalent.

#### **FIRE REGULATIONS**

Normally it is a requirement of any Lease or Tenancy agreement that current fire regulations are adhered to and that a service contract is in place. This is how the property should be left.

**ACTION REQUIRED:** You should have a suitable Fire Safety Notice from the outgoing tenant/landlord.

#### **DISABILITY DISCRIMINATION ACT**

You should be aware that it is now a requirement to give reasonable access to the disabled and make reasonable amendments to the property as is necessary to accommodate them. It is a condition of all the leases that we have seen to meet this requirement.

**ACTION REQUIRED:** You should ask to see if a report has been carried out in line with the Disabilities Act highlighting areas that can be improved or have been improved.

#### **ASBESTOS REGISTER**

In a property of this age there may well be some asbestos. This was commonly used post war until it was banned only in the last ten or so years, although it is rumoured that it was still used after this point in time.

It is now a requirement for any public building to have an asbestos register, indicating whether there is or is not asbestos and if so where it is.

**ACTION REQUIRED:** An Asbestos Register should be provided by the outgoing tenant/landlord.

You should note that work involving products containing asbestos is covered by Health and Safety legislation and you are recommended to seek the advice of the Local Authority Environmental Health Officer before proceeding with any such work.

We are not asbestos surveyors.

#### **LIMITATIONS**

As per our original Terms of Engagement, we would remind you specifically that:

We have not inspected parts of the structure that were covered, unexposed or inaccessible during our inspection. We therefore cannot confirm that such parts are free from defect, structural or otherwise.

We have not determined whether any hazardous materials such as high alumina cement, calcium chloride, asbestos etc have been used in the construction.

Our report is for the use of the party to whom it is addressed above and no responsibility is accepted under the Third Parties Act or for any third parties who use this report in whole or in part.

We have not carried out a comprehensive test of any electrical, mechanical or drainage services. We therefore cannot confirm that they are operational and in good condition. If you wish us to arrange tests please advise.

We have not carried out or arranged for specialists to undertake any reports, for example an environmental report or an audit report upon the property. We are therefore unable to advise whether any contaminated or other adverse environmental issues affect the site.

This report does not constitute a Structural Survey (now known as a Building Survey).

74

#### Signature Document in Relation to a Restaurant in Hertfordshire

#### **Schedule of Condition**

This signature document represents page 76 and 77 of a 77 page Schedule of Condition relating to:

A Restaurant In Hertfordshire

as prepared by

**Chartered Surveyors** 

You should ensure your Legal Advisor gets this document signed by the relevant parties and agreed prior to legal commitment to purchase. Delete/amend as you require.

#### **Lessees Representative**

We verify that this is a true and accurate record of the condition of:

A Restaurant In Hertfordshire

As inspected

By

Chartered Surveyors

Signed: ...... Dated:

For and on Behalf of Chartered Surveyors

# Lessee Miss Q has seen and forwarded this document on by recorded delivery on owners/landlords the or their to legal representatives in relation to the proposed Lease. Signed: ...... Dated: ...... Miss Q **Landlords Representative (delete as applicable)** Print Name: ..... for and on behalf of ...... has inspected and read the Schedule of Condition for an on behalf of ..... and accepts that it is a true and accurate record.

I have the authority to sign this document on behalf of the aforementioned company.

Signed: ..... Dated: .....

For and on Behalf of: