Property Eras

in Photos

Early Victorian Era

EXTERNAL

Front View



Right hand side and bridge



Rear view



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Right hand side



Parking area to rear



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Culvert stream



INTERNAL Ground Floor

Entrance hallway



Corridor



Reception room one



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Reception room two



Reception room three



Kitchen!



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Utility room



INTERNAL First Floor

Landing



Master bedroom to front



Bedroom two to the rear



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Bedroom three to the rear



not to be used in any format without express written permission

Bedroom four to the front



Bathroom to the rear



Shower room



not to be used in any format without express written permission

Property Issues

Roof to the rear



Roof space/loft



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Roof meeting adjoining property



Ceiling to master bedroom





not to be used in any format without express written permission

Front bay roof



Walls



Windows



Floors



Floors



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

Walls



not to be used in any format without express written permission



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission



Copyright of 1stAssociated.co.uk not to be used in any format without express written permission

